

DEPARTMENT OF THE AIR FORCE
SHADOW MOSES AIR FIELD, ALASKA

WALL-CONDITION REPORT

Building 100 SIPR Room 1-126 | Reported after Government possession

Report number	CES-CP-28-0914-03
Observed / reported	14 September 2028 / 0815 and 0840 Alaska time
Observer	Dr. Hal Emmerich, Chief Facilities Engineer, 713 CES
Possession began	10 September 2028 / 0700 Alaska time
Location	Room 1-126, broad north wall, finish designation A-17

Observed condition

A long horizontal scratch cuts through the blue-gray finish coat on Wall A-17. The exposed line is approximately 58 inches long, varies from 1/8 to 3/8 inch in height, and is centered approximately 44 inches above finished floor. No substrate fracture, moisture, loose gypsum, or security-system damage is visible.

Record check	Result	
O-01 remaining-work list	Does not identify repair of Wall A-17	
Room use since possession	Sneaking Mission briefings and routine Command Post access	
Contractor access	Two escorted ceiling-label work periods; no recorded Wall A-17 repair	
Cause / time of damage	NOT ESTABLISHED BY THIS REPORT	
ACTION REQUESTED: Contracting should determine when the condition arose and which contract record controls before directing repair, assigning cost, or treating the condition as Government-caused damage.		
Signed	Name / position	Date
/s/ Hal Emmerich	Hal Emmerich Chief Facilities Engineer, 713 CES	14 Sep 2028

Record note: The measurements and observations are fictional exercise facts. This report records condition, not responsibility or acceptance.